



Work Shop Reggie's Motorworks

Tel. 317-773-0074

Address: 1362 South 10th Street, Noblesville, IN 46060

Report No. TOPDON1705351510

Date Created: 2024-01-15



Diagnostic Report

Plate No.

Make: PORSCHE

Model: 986Boxster

Year: 2003

Mileage:

Engine:

Sub Model:

Ticket No.:

Diagnostic Time: 2024-01-15 15:45:10

Vehicle Software Ver. V1.70

Diagnostic App Ver. V1.10.005

VIN: WP0CA29823U622773

Diagnostic Path Automatic/PORSCHE/986Boxster/2003/
System list

Customer:

Customer Tel.

Summary

3 systems were scanned, and 0 of them were detected with DTCs. Altogether 0 DTCs were found. For safe driving, please read the report carefully and perform related repair in a timely manner.

System Report(3)

Pre-Scan	
System	DTC
DME(Digital Engine Module)	No fault 0
ABS(Anti-lock Brake System)	No fault 0
Airbag	No fault 0

Disclaimer



Work Shop Reggie's Motorworks

Tel. 317-773-0074

Address: 1362 South 10th Street, Noblesville, IN
46060

Report No. TOPDON1705351510

Date Created: 2024-01-15

This test report is meant to be used as a reference for vehicle inspection and maintenance. TOPDON shall not be liable for any accident or failure arising therefrom. Any illegal transfer, embezzlement, imposture, modification or tampering is prohibited, and TOPDON has the right to take legal actions.